

Nitta Corporation of America

7605 Nitta Drive
Suwanee, GA 30024
800-221-3689
Fax: 770-623-1398
www.nitta.com



Tension Table

% Tension	Distance between marks with no tension on belt			
	<u>1000mm</u>	<u>500mm</u>	<u>100in</u>	<u>50in</u>
	Distance between marks with given tension on the belt			
0.10	1001mm	500.5mm	100.1in	50.05in
0.20	1002mm	501mm	100.2in	50.1in
0.30	1003mm	501.5mm	100.3in	50.15in
0.40	1004mm	502mm	100.4in	50.2in
0.50	1005mm	502.5mm	100.5in	50.25in
0.60	1006mm	503mm	100.6in	50.3in
0.70	1007mm	503.5mm	100.7in	50.35in
0.80	1008mm	504mm	100.8in	50.4in
0.90	1009mm	504.5mm	100.9in	50.45in
1.00	1010mm	505mm	101in	50.5in
1.25	1012.5mm	506.25mm	101.25in	50.625in
1.50	1015mm	507.5mm	101.5in	50.75in
1.75	1017.5mm	508.75mm	101.75in	50.875in
2.00	1020mm	510mm	102in	51in
2.25	1022.5mm	511.25mm	102.25in	51.125in
2.50	1025mm	512.5mm	102.5in	51.25in
2.75	1027.5mm	513.75mm	102.75in	51.375in
3.00	1030mm	515mm	103in	51.5in